



Department of Energy

ROCKY FLATS OFFICE
P.O. BOX 928
GOLDEN, COLORADO 80402-0928

DEC 04 1992

DEC 8 1992

8HWM-FF
92-DOE-13642

Mr. Martin Hestmark ✓
U.S. Environmental Protection Agency, Region VIII
ATTN: Rocky Flats Project Manager, 8HWM-RI
999 18th Street, Suite 500, 8WM-C
Denver, Colorado 80202-2405


Mr. Gary Baughman
Hazardous Waste Facilities Unit Leader
Colorado Department of Health
4300 Cherry Creek Drive South
Denver, Colorado 80222-1530

Gentlemen:

We are submitting copies of the document entitled: "Observations on the Occurrence of Plutonium and Americium in Ground and Surface Water, Rocky Flats Plant, 903 Pad, Mound, and East Trenches, Operable Unit 2." This document was prepared as a result of the decision to pursue the OU 2 Subsurface Interim Measure/Interim Remedial Action (IM/IRA) rather than the Woman Creek Seeps IM/IRA. The preparation of this document was delayed due to data accuracy problems associated with the Rocky Flats Environmental Data System and due to extensive internal review.

If you have any questions, please contact Scott Grace at 966-7199.

Sincerely,


James K. Hartman
Assistant Manager
for Environmental Management

Enclosure

cc w/Enclosure:
A. Rampertaap, EM-453
J. Ciocco, EM-453

cc w/o Enclosure:
M. Buddy, EG&G
T. Greengard, EG&G
E. Dille, EG&G
M. Harris, EG&G
B. Fraser, EPA
J. Schieffelin, CDH

ADMIN RECORD

A-DU02-000472



Department of Energy

ROCKY FLATS OFFICE
P.O. BOX 928
GOLDEN, COLORADO 80402-0928

DEC 04 1992

92-DOE-13642

Mr. Martin Hestmark
U.S. Environmental Protection Agency, Region VIII
ATTN: Rocky Flats Project Manager, 8HWM-RI
999 18th Street, Suite 500, 8WM-C
Denver, Colorado 80202-2405


Mr. Gary Baughman ✓
Hazardous Waste Facilities Unit Leader
Colorado Department of Health
4300 Cherry Creek Drive South
Denver, Colorado 80222-1530

Gentlemen:

We are submitting copies of the document entitled: "Observations on the Occurrence of Plutonium and Americium in Ground and Surface Water, Rocky Flats Plant, 903 Pad, Mound, and East Trenches, Operable Unit 2." This document was prepared as a result of the decision to pursue the OU 2 Subsurface Interim Measure/Interim Remedial Action (IM/IRA) rather than the Woman Creek Seeps IM/IRA. The preparation of this document was delayed due to data accuracy problems associated with the Rocky Flats Environmental Data System and due to extensive internal review.

If you have any questions, please contact Scott Grace at 966-7199.

Sincerely,


James K. Hartman
Assistant Manager
for Environmental Management

Enclosure

cc w/Enclosure:
A. Rampertaap, EM-453
J. Ciocco, EM-453

cc w/o Enclosure:
M. Buddy, EG&G
T. Greengard, EG&G
E. Dille, EG&G
M. Harris, EG&G
B. Fraser, EPA
J. Schieffelin, CDH

ADMIN RECORD

